## R10 Recreation Facility Inventory and Condition Report

Presentation to Recreation and Socioeconomic Workgroup 10/30/03



FERC Project No. 2100


Oroville Facilities Relicensing



**OWA Area G Dispersed Camping.** 



**Bloomer Cove Campsite.** 



**Craig Saddle Boat-in Camp restroom.** 



Foreman Creek Boat-in Camp approach.




Floating Campsite #4.







**Loafer Creek DUA.** 





Lime Saddle Boat Ramp.




**Loafer Creek Multi-Use Trail.** 










Recreation sites with all facilities in good condition.			
Aquatic Center	Larkin Road (Thermalito Afterbay) Car-top BR		
Bidwell Canyon BR/DUA	Lime Saddle Campground		
Bidwell Canyon Campground	Lime Saddle Group Campground		
Bidwell Canyon Trail	Lime Saddle BR/DUA		
Bloomer Point BIC	Loafer Creek BR/DUA		
Brad P. Freeman Trail	Loafer Creek Campground		
Chaparral Interpretive Trail	Loafer Creek Group Campground		
Clay Pit State Vehicular Recreation Area	Loafer Creek Horse Campground		
Craig Saddle BIC	Model Aircraft Flying Area		
Dan Beebe Trail	Monument Hill BR/DUA		
Diversion Pool DUA	North Thermalito Forebay RV "En Route" Campground		
East Hamilton Trailhead Access	Oroville Dam		
Feather River Fish Hatchery	Roy Rogers Trail		
Floating Campsites	Saddle Dam Trailhead Access		
Floating Restrooms	Spillway BR/DUA		
Goat Ranch BIC	Spillway RV "En Route" Campground		
Lake Oroville Visitors Center			

Recreation facilities in need of maintenance, repair, or replacement.				
Recreation Location	Maintenance Needed	Repair Needed	Replacement Needed	
Afterbay Outlet Boat Ramp	-	Pave boat ramp	-	
Bloomer Cove BIC	Restroom	-	-	
Bloomer Group BIC	Restroom		<u>-</u>	
Bloomer Knoll BIC	Restroom	-		
Dark Canyon Car-top BR	Garage facilities	- 1 -	Directional sign	
Enterprise BR	Garbage facilities		- 1 -	
Foreman Creek BIC	Restroom	-	-	
Foreman Creek Car-top BR	Garbage facilities		-	
Lime Saddle Marina	-	Marina facilities		
Nelson Bar Car-top BR		Boat ramp shoulder		
North Thermalito Forebay BR/DUA	Interpretive display			
OWA (Afterbay Outlet Camping Areas C, F, and G)			Directional sign	
OWA (Afterbay Outlet Camping Area G)	Secondary gravel/dirt road, restroom	-		
Rabe Road Shooting Range	-		Directional signs	
South Thermalito Forebay BR/DUA	Interpretive display			
Stringtown Car-top BR	Garbage facilities	Boat ramp shoulder	Directional signs	
Vinton Gulch Car-top BR			Directional signs	
Wilbur Road (Thermalito Afterbay) BR	Garbage facilities			

## Other Facility Issues

- Gas pumps at the Bidwell Marina not available at the lowest reservoir levels.
- Presence of sensitive cultural resources at Foreman Creek Car-top BR and Enterprise BR.
- The OWA boat ramps are unimproved and are not in good condition & are not scheduled to be upgraded except for the Outlet area ramp.
- Outlet area ramp is scheduled to be upgraded.

**Project Area Associated Recreation Sites and Conditions.** 



## R10 Recreation Facility Inventory and Condition Report

Presentation to Recreation and Socioeconomic Workgroup 10/30/03



FERC Project No. 2100

Oroville Facilities Relicensing